## **EAST Search History**

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	147	(tape) and (inspection or calibration) and (meander)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	NEAR	ON .	2008/01/14 13:07
L2	5	(tape) and (inspection or calibration) and (meander) and (tape near6 meander)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	NEAR	ON	2008/01/14 13:11
L3	11	(tape) and (inspection or calibration) and (meander) and (tape same meander)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	NEAR	ON	2008/01/14 13:11

## **EAST Search History**

Ref #	Hits	Search Query	DBs .	Default Operator	Plurals	Time Stamp
L1	0	((tape) and (inspection or calibration or test) and (servo) and (meander)). clm.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	NEAR /	ON	2008/01/14 14:05

Page 1